



## Sandy Hook Community Association

5916 Skookumchuk Road,  
Sechelt, BC, V0N 3A4  
Email: sandyhook@sechelt.net  
Web site: <http://sechelt.net>

**BY EMAIL** in pdf format

August 27, 2007

Mr. Ken Tang  
Director of Engineering & Public Works  
District of Sechelt  
2nd Floor 5797 Cowrie St.  
PO Box 129, Sechelt, BC  
V0N 3A0

Dear Ken,

Re: Seaview Road Problem and Danger

At the meeting of August 20, 2007 the board directed that I write you again on this matter but this time copy in the Mayor and the Administrator. The extra copies are only to see that the issue is properly recorded for the future.

We have written you by email in March and June and July to point out that the drainage at the "intersection" of Seaview Road and Sandy Hook Road seems to have been improperly installed following the renewal of the water mains. Various SH members, who apparently have some expertise in this field, are convinced that with heavy rains over a period the road will fail. That will mean the isolation of all of lower Sandy Hook and a very substantial bill to taxpayers for rebuilding. Currently, there is a serious danger to drivers who hit the sheets of water going across the road.

We understand that since March the matter has been the subject of some discussion with the SCR D but there has been no action to date.

We cannot see continuing to write reminders of concern and so this will probably be our last attempt to stimulate action. We will leave the solution and the consequences to the District with this official recording of the problem.

Thank you very much.

Yours truly,  
Sandy Hook community Association

Per: *Robert B. D'Arcy* (computer signature)

Secretary Treasurer

cc:

The Mayor – His Worship Cameron Reid  
The District Administrator – Mr. Bill Brown